

1/3





Fig.2





2/3

Fig.3(a)




Fig. 3(b)





Fig.4



DOCKET NO.: 8041-1018 APPLN NO.: 09/847,370 REPLY TO NOTICE OF ALLOWABILITY OF: MARCH 9, 2004 REPLACEMENT SHEET

3/3

Fig. 5(a) PRIOR ART




Fig. 5(b) PRIOR ART

503:SOLDERING LAND




Fig.6 PRIOR ART

